





PARISH OFFICE & RECTORY RENOVATION PROJECT





Basement Level West Wing- Before Renovation.....	Page 3
Basement Level West Wing- After Renovation (CGS Space)	Page 4
Basement Level East Wing- Before Renovation.....	Page 5
Basement Level East Wing- After Renovation (CGS Space)	Page 6
First Floor West Wing- Before Renovation.....	Page 7
First Floor West Wing- After Renovation (Meeting Spaces)	Page 8
First Floor East Wing- Before Renovation	Page 9
First Floor East Wing- After Renovation (St. John Paul II Chapel)	Page 10
First Floor Sacristy Hallway - Before & After Renovation	Page 11
Second Floor West Wing- Before Renovation.....	Page 12
Second Floor West Wing- After Renovation (Offices/Meeting Room)...	Page 13
Second Floor East Wing- Before Renovation.....	Page 14
Second Floor East Wing- After Renovation (Offices/Meeting Room)	Page 15
Third Floor West Wing- Before Renovation	Page 16
Third Floor (Guest Rooms) West Wing- After Renovation.....	Page 17
Third Floor East Wing- Before Renovation.....	Page 18
Third Floor (Pastor's Residence) East Wing- After Renovation.....	Page 19
Open House Recap - November 12, 2023	Page 20


BASEMENT LEVEL

PAGE 3










Basement West Wing - Before Renovation





Catechesis of the Good Shepherd West Wing - After Renovation




BASEMENT LEVEL

PAGE 5





Basement East Wing - Before Renovation






Catechesis of the Good Shepherd East Wing - After Renovation



FIRST FLOOR




First Floor West Wing - Before Renovation




FIRST FLOOR



First Floor Meeting Spaces West Wing - After Renovation



FIRST FLOOR



First Floor East Wing - Before Renovation



FIRST FLOOR



First Floor St. John Paul II Chapel, Workroom - After Renovation




FIRST FLOOR

Before Renovation



First Floor Sacristy Hallway - Before & After Renovation

After Renovation



SECOND FLOOR




Second Floor West Wing - Before Renovation



SECOND FLOOR



Second Floor Offices & Conference Room West Wing - After Renovation




SECOND FLOOR







Second Floor East Wing - Before Renovation



SECOND FLOOR



Second Floor Offices & Conference Room East Wing - After Renovation




THIRD FLOOR



Third Floor West Wing - Before Renovation



THIRD FLOOR



Third Floor Guest Rooms West Wing - After Renovation




THIRD FLOOR





Third Floor East Wing - Before Renovation



THIRD FLOOR



Third Floor Pastor's Residence East Wing - After Renovation



OPEN HOUSE - NOV 12, 2023

